



Criterion VII

Institutional Values and Best Practices


7.1 – Institutional Values and Social Responsibilities: (2024-2025)

7.1.3 – The Institution has facilities for alternate sources of energy and energy conservation devices:

- a. Solar energy**
 - b. Wheeling to the grid**
 - c. Sensor based energy conservation**
 - d. Biogas plant**
 - e. Use of LED bulbs/ power efficient equipment.**
- Any other relevant information.**

राहुल भारत रणदिवे

सर्व सोलर व सोलर water हिटर दुरुस्ती/ बाराटे चाक संजीवन हॉस्पिटल जवळ वारजे माळवाडी				
प्रती मद्यी कर्ते री दिक्षण सस्था		बिल न - 149	मो न - ९७६३२६३४२५	
रमासदन		दिनांक 28/05/25	NPAN नं - AZHPR5305H	
अ क्र	कामाचा तपशील	Qty	दर	रक्कम
①	मिळण असलेल्या सोलर घुळ काढण भासिक सिलीकॉन वायसर श्वराक असलेले काढण नकिंग सिलीकॉन वायसर भायुग थुळा भायुग मिळण कंद करण देणे .	27 नग x	200	5400 = 20
②	श्वराक असलेल्या कायरेक किरिंग काढण नकिंग कापलेक किरिंग कासयुन देणे कळिकेक कंद करणे .	3 नग x	200	600 = 20
			एकूण	6000 = 20
अक्षरी रुपये सहा हजार रणदिवे .			राहुल भारत रणदिवे . राहुल भारत रणदिवे करिता	



Bill of Repairing

Rahul Bharat Randive

All prober and sober water heater repair/ near Barate Chal Sanjeevan Hospital
Warje Malwadi

Bill No 149
Dated 28/05/25
NPAN No. AZHPR5305H
Mo No. 9763263425

To,
MKSSS Ramasadan

SR.NO	DETAILS OF WORK	QTY	RATE	AMOUNT
1	Remove the leaking solar puck and cut the leaky silicone visor and apply silicone cotton to the center of the leak.	27	200	5400
2	Remove the firing from a sharp knife and replace it with a new cut firing.	3	200	600
			Total	6000/-

MKSSS ESTATE DEPT.

SD/-

श्री. प्रमोद .

सॅनिटेशन गार्डनिंग/रिपेअर्स मेंटेनन्स/सिक्क्युरिटी Ramasadan Hostel.
कामाचे नांव Changing Solar leakage tubes and
wiser to tubes. etc. work complete

सभा मंजूरी दिनांक:

उराव क्रमांक:

मंजूर रक्कम:

कामाची पद्धत-कोटेशन टेंडर/मोलमजूरीने/लेबर ठेकेदार labour bill

स्पर्धात्मक तक्ता मंजूरी दिनांक


Suresh Pawar
16/6/25


17/6/25
वास्तूव्यवस्थापक (वरिष्ठ)

महर्षी कर्वे स्त्री शिक्षण संस्था

कर्वेनगर, पुणे ४११०५२

प्रति,
मा. प्रमुख

गेटपास

नं. 1927

दिनांक : 24/5/25

Remasadhani;

कामाचे स्वरूप Solar pipe leakage Repairing
ठेकेदाराचे नाव Pahul Banlive

मजुरांची नावे खालीलप्रमाणे :

अनु. क्र.	मजुरांची नावे	मिस्त्री	गडी	बाई
१	Pahul Banlive	०१		
२	Santosh Misal	०१		
३				
४				
५				
६				
७				
८				
९				
१०				
११				
१२				
	एकूण	०२		

~~10/5/25~~
सुपरवायझरची सही

२६/०५/२०२५
१ ठेकेदाराची सही

शेरा

वास्तुव्यवस्थापक

शाखाप्रमुखाची सही